## FIG. 1







FIG. 2



KITTA et al Q67188 ON-VEHICLE ELECTRONIC CONTROLLER Filed: November 14, 2001 Robert J. Seas, Jr. 202-293-7060 3 of 8


FIG. 3






KITTA et al

Q67188 ON-VEHICLE ELECTRONIC CONTROLLER KITTA et al Q67188 ON-VEHICLE ELECTRONIC CONTROLLER Filed: November 14, 2001 Robert J. Seas, Jr. 202-293-7060 5 of 8



KITTA et al Q67188 ON-VEHICLE ELECTRONIC CONTROLLER Filed: November 14, 2001 Robert J. Seas, Jr. 202-293-7060 6 of 8


FIG. 6



The limit of the l

KITTA et al Q67188 ON-VEHICLE ELECTRONIC CONTROLLER Filed: November 14, 2001 Robert J. Seas, Jr. 202-293-7060 7 of 8

FIG 7



KITTA et al Q67188 ON-VEHICLE ELECTRONIC CONTROLLER Filed: November 14, 2001 Robert J. Seas, Jr. 202-293-7060 8 of 8

FIG. 8

